



**Graphite** is the ideal lubricant for a speedometer cable, but getting it into the cable sheathing may be a problem. Here's one way of doing it: remove the inner cable, lay it on a board, apply the thinnest possible line of light oil on it, spray powdered graphite on the oil until the oil is blotted up and replace the inner cable.



**A head gasket** can be checked for leakage by adding two spoonfuls of washing bluing to a cup of permanent antifreeze, pouring it into the radiator, tying a cloth over the tailpipe and running the engine. If there's a leak the bluing will color the cloth. The antifreeze will help you in locating the leaky trouble spot.



**Windshield fog and steam** can be wiped away quickly with a cellulose sponge. It will remove dirt and grease streaks and absorb considerable moisture before becoming saturated. A small inexpensive sponge will do the trick.



**If sand is carried** in a couple of one-gallon, screw-top cans, you can simply pour it under the tires when you get stuck on ice or snow. No need for a shovel to spread it. The cans are better than a box, for the sand can't scatter through the trunk.