




Hints from the Model Garage




To increase idling speed temporarily when you charge the battery with the generator, or warm the engine, insert a burnt match between the carburetor idle screw and its stop. When you step on the throttle, the match will drop away.



Protect your hands from contact with chilled metal by slipping a length of heater hose over the shank of your lug wrench. The hose will also keep the wrench from marring rims or whitewalls when prying off wheel covers.



Frayed door piping can be improved in appearance, or the piping in a new car protected, by covering it with flexible clear-plastic tubing. Slit the tubing along one side and force it over the piping. Tuck the ends under the metal step plates.



Fool old man winter by placing several synthetic sponges and a plastic bag inside the windshield-washer bottle. Fill the bag with water and solvent. If the solution should freeze, the sponges and bag will allow for expansion.